

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 99990080/82-02(DETP)

Docket No. 99990080

Licenses No. XSNM-1444; XSNM-1668; XSNM-1808;  
XSNM-1824; XSNM-1825; XSNM-1840;  
XSNM-1891; XSNM-1905; XSNM-1924

Licensee: Transnuclear, Incorporated  
One North Broadway  
White Plains, NY 10601

Inspection At: Point of Origin and Partial In-Transit Surveillance

Inspection Conducted: August 19, 1982

Type of Inspection: Routine Safeguards Inspection of Nuclear Material

Inspector: *J. L. Belanger for*  
T. J. Madeda  
Physical Protection Specialist

8/31/82

Approved By: *J. L. Belanger for*  
J. R. Creed, Chief  
Safeguards Section

8/31/82

Inspection Summary

Inspection on August 19, 1982 (Report No. 99990080/82-02(DETP))

Areas Inspected: Included a review of General Performance Objectives; In-Transit Performance, General Physical Protection System Requirements; Security Organization and Audit; Response and Contingency Plan/Procedures; Access Control; Testing and Maintenance; Road Shipment Requirements; and Delivery and Receiving Requirements. The inspection involved five inspector-hours onsite by one NRC inspector. The inspection began during an off-shift period.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during the inspection.

(Details - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure Contains  
SAFEGUARDS INFORMATION  
Upon Separation This  
Page is Decontrolled

8209080084 820831  
IE GA999 EMVTRNC  
999990080 PDR