(7-91) 10 CFR 2,201

SAFETY INSPECTION

Page 1 of

		Page 1 of 1
UCENSEE Thread University Invironmental Realth and 46 Oxford Street Cambridge, Hassachungsta	Safety	REGION I US NUCLEAR REGULATORY COMMISSION 475 ALLENDALE ROAD KING OF PRUSSIA PA 19406-1415
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE UF INSPECTION
030-10160 030-15244	20-00297-50 20-00297-59	Tebruary 20, and Barch 1, 1994
Regulatory Commission (NRC) rules and re	egulations and the conditions of your	se as they relate to radiation safety and to compliance with the Nuclea license. The inspection consisted of selective examinations of lons by the inspector. The findings as a result of this inspection are a
Within the scope of this inspection	on, no violations were observed.	
The inspector also verified the st questions on those actions at this		lations identified during the last inspection. We have no further
	your activities, as described below or s required to be posted in accordance	attached, were in violation of NRC requirements. This form is a with 10 CFR 19.11.
- A		was not properly posted to
ind: ate the presence of a		10 CFR 20.203(b),(c),(d),(e) or 34.42
В.		of sealed sources were not
performed at the proper fr	equencies, 10 CFR	or License Condition Number
G. Records of		were not properly maintained.
10 CFR	or License Condition Number	
	erly posted or otherwise made availal	
E. Reports or notification of		were not made in accordance with
10 CFR		
	anners of Laurine Committee receives	
DESIGNATED ORI	GINAL	
Certified by 70.	a. Perkins	

SIGNATURE - NRC INSPECTOR

SIGNATURE - LICENSEE DATE
9403290049 940311
PDR ADDCK 03010180
C PDR

NRC FORM 591 Part 1 (7-91) RETURN UNICHNAL TO
REGION 1

DATE

3/11/94