



DEPARTMENT OF THE NAVY

USS YOSEMITE (AD 19)
FPO. MIAMI, FLORIDA 34083

AD19:QA:wh
9673
Ser 033

JAN 11 1983


From: Commanding Officer, USS YOSEMITE (AD 19)
To: Commanding Officer, U. S. Nuclear Regulatory Commission Region II
Subj: Notice of Violations; response and corrective action to
Ref: (a) Chief Technical Inspection Branch, U. S. Nuclear Regulatory
Commission Region II ltr of 22 Oct 1982

1. In response to reference (a), received 14 Dec 1982, the following explanatory information is submitted.

a. Appendi: A, Notice of Violation of reference (a), identified that the Repair Office had not performed the required audits of the radiographic facility in accordance with NRC License No. 31-17802-01. No audit of the radiographic facility could be performed from October 1982 to November 1982. During this period, there was no radiographic source in the custody of the USS YOSEMITE. During the fourth quarter of 1981, the only radiographic operation involved the receipt inspection of the source and container which were completed satisfactorily and reported to the Repair Officer. From January 1982 to September 1982, all radiographic operations were closely monitored with reports forwarded to the Repair Officer.

b. The quarterly internal audit program has been reestablished with satisfactory results. The fourth quarter audit of the radiographic facility for 1982 has been completed. In the future, the required audits will be performed within each quarter and filed as required.

2. Full compliance was achieved by 8 Oct 1982.


T. H. ROBERTS

Copy to:
RO, AD 19
RSO, AD 19
QAO, AD 19
Senior Radiographer, AD 19
NDT, AD 19

8302150668 830131
NMS LIC30
31-17802-01 PDR