



Portland General Electric Company
Trojan Nuclear Plant
P.O. Box 439
Rainier, Oregon 97048
(503) 556-3713

RECEIVED
NRC

1982 AUG 25 AM 11:27

August 20, 1982
CPY-662-82

REGIONS USE

50-344

Mr. R. H. Engelken
Regional Administrator
US Nuclear Regulatory Commission
1450 Maria Lane - Suite 210
Walnut Creek, California 94595-5368

Dear Sir:

Subject: Immediate Report of Reportable Occurrence

This letter is a follow-up to a verbal report made by Don Pearson, Trojan Shift Supervisor, to Mike Malmros, USNRC Resident Inspector, and the NRC Operations Center via the automatic ring-down NRC notification circuit (red phone). The notification concerned a situation where both trains of the automatic safety injection signals were blocked. Both trains of automatic safety injection were disabled for 43-hours while in Modes 3 and 4 which is in excess of the 6-hour time limit specified in the Technical Specification limiting conditions for operation, 3.3.2.1.

Upon discovery on August 20, 1982 at 1130 hours both trip breakers were closed which unblocked both trains of the automatic safety injection system.

This occurrence will be reported to the Nuclear Regulatory Commission as a Licensee Event Report in accordance with our established Technical Specifications.

Sincerely,

C. P. Yundt
General Manager

CPY/DJK

c: LER Distribution
File 93.24a(Q)

8209080168 820820
PDR ADOCK 05000344
S PDR

IE-29