DMB

TE:35



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

Docket No. 50-254 Docket No. 50-265

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This confirms our plans to meet with you and members of your staff at 8:30 a.m. on September 9, 1982, in our Region III office in Glen Ellyn, Illinois.

The purpose of the meeting will be to discuss deficiencies in emergency preparedness that were recently identified by Dr. C. Paperiello and Mr. M. Phillips of my staff. A copy of the meeting agenda is enclosed.

We will gladly discuss any questions you have concerning this matter.

Sincerely,

a Birt A

\$1'm. 1.

James G. Keppler Regional Administrator

Enclosure: As stated

8209080170 8209 PDR ADOCK 05000

cc w/encl: Louis 0. DelGeorge, Dir. of Nuclear Lic. N. Kalivianakis, Plant Supt. DMB/Document Control Desk (RIDS) Resident Inspector, RIII Karen Borgstadt, Office of Assistant Attorney General

COMMONWEALTH EDISON ENFORCEMENT CONFERENCE CONCERNING EMERGENCY PREPAREDNESS ISSUES MEETING AGENDA

- 1. Status of offsite preparedness for Scott and Clinton Counties as it relates to the operation of Quad-Cities Station.
 - a. Offsite deficiencies identified
 - b. Enforcement Actions Proposed
 - c. Commonwealth actions to correct deficiencies
- 2. Status of onsite preparedness for Quad-Cities, Dresden, Zion, and LaSalle
 - a. Revisions to Site Specific Annexes to correct identified deficiencies
 - Use of the term "should" in light of recently discovered Commonwealth policy statements
 - c. NRC review of all onsite plans in light of 2.b above
 - d. Enforcement actions proposed
 - e. Commonwealth actions to correct deficiencies
- Status of Prompt Fublic Notification System in the vicinity of Quad-Cities Station as it relates to the requirement to provide prompt instructions to the public.

· so al Prover

- a. Deficiencies identified
- b. Enforcement actions proposed
- c. Commonwealth actions to correct deficiencies
- 4. Problems identified regarding scenario development
 - a. NRC Concerns

La.

- (1) Technical errors
- (2) Last-minute changes
- (3) Lack of sufficient operational data
- b. Commonwealth actions to resolve concerns