

Georgia Power Company
333 Piedmont Avenue
Atlanta, Georgia 30308
Telephone 404 526 6526

Mailing Address
Post Office Box 4545
Atlanta, Georgia 30302

NRG REGION
II

83 FEB 3 8 1 - 21

Power Generation Department



Georgia Power

the southern electric system

NED-83-023

January 31, 1983

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II - Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303

REFERENCE:
RII: JPO
50-366
I&E Bulletin
80-16

ATTENTION: Mr. James P. O'Reilly

GENTLEMEN:

In our response of December 14, 1982, regarding the subject bulletin, we stated that: "As part of the upcoming Unit 2 outage, we intend to replace the Model 1151 transmitters with Model 1153B transmitters."

Due to engineering design problems, installation will be delayed until the Unit 2 refueling outage at the end of cycle 4 (i.e., Spring 1984). Further, it is our intention, based on current engineering design, to replace the 1151A and 1151D transmitters in the MSIV leakage control system with equipment qualified per NUREG-0588, but not necessarily the Model 1153B transmitters.

If you have any further questions, please contact this office.

Very truly yours,

L. T. Gucwa
Chief Nuclear Engineer

MJB/mb

xc: J. T. Beckham, Jr.
H. C. Nix, Jr.
Senior Resident Inspector

8302150702 830131
PDR ADOCK 05000366
Q PDR

IE11