

Laudan  
Info



# BRAND-REX COMPANY

WILLIMANTIC, CONNECTICUT 06226 • 203/423 7771

ELECTRONIC AND INDUSTRIAL CABLE DIVISION

August 12, 1982

82-685-000 R. DeYoung, JE

50-312

~~BAE~~

Part-21

U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, TX 76011

Attention: Mr. John Collins

Subject: Title 10 Chapter 1 Code of Federal Regulation  
Part 21. Report.

AUG 17 1982  
*[Signature]*

### Informant

Brand-Rex Company  
Willimantic, CT 06226

### Supplied

Sacramento Municipal Utility District  
Rancho Seco Nuclear Power Plant  
Herald, CA

### Supplier

Brand-Rex Company

### Notation of Defect

White powder covers two conductors cable jacket.  
Jacket material appears to have been effected  
due to storage in adverse environmental conditions.

### Safety Hazard

Undetermined at this time

Date information was obtained

May 4, 1982

8209080277 820812  
PDR PT21 EMVBREX  
82-685-000 PDR

IE 19

Number and Location

One location - SMUD - Rancho Seco  
Nuclear Power Plant, Herald, CA

Corrective Action


Cable has been removed from site  
and sample of cable returned for chemical analysis

At this time, Brand-Rex has no findings pertaining to problem area.

Explanation of condition, and method to be employed to detect  
problem area will be developed and submitted as part of corrective action.

Very truly yours,

BRAND-REX COMPANY  
A Part of Akzona, Inc.

  
\_\_\_\_\_  
Louis B. Roberts  
Quality Assurance Manager

cjs  
cc: G. Graeber  
E. Walton



# BRAND-REX COMPANY

WILLIMANTIC, CONNECTICUT 06226 • 203/423-7771

August 12, 1982

U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, TX 76011

AUG 17 1982

Attention: Mr. John Collins

Subject: Title 10 Chapter 1 Code of Federal Regulation  
Part 21. Report.

## Informant

Brand-Rex Company  
Willimantic, CT 06226

## Supplied

Sacramento Municipal Utility District  
Rancho Seco Nuclear Power Plant  
Herald, CA

## Supplier

Brand-Rex Company

## Notation of Defect

White powder covers two conductors cable jacket.  
Jacket material appears to have been effected  
due to storage in adverse environmental conditions.

## Safety Hazard

Undetermined at this time

Date information was obtained

May 4, 1982

Number and Location

One location - SMUD - Rancho Seco  
Nuclear Power Plant, Herald, CA

Corrective Action

Cable has been removed from site  
and sample of cable returned for chemical analysis

At this time, Brand-Rex has no findings pertaining to problem area.

Explanation of condition, and method to be employed to detect  
problem area will be developed and submitted as part of corrective action.

Very truly yours,

BRAND-REX COMPANY  
A Part of Akzona, Inc.

---

Louis B. Roberts  
Quality Assurance Manager

cjs  
cc: G. Graeber  
E. Walton