

FEB 1 1983

APPENDIX A

NOTICE OF VIOLATION

Ampco - Pittsburgh Corporation  
Cornwells Heights, Pennsylvania 19020

Docket No. 30-6160  
License No. 37-07219-01

As a result of the inspection conducted on January 12, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

Condition 17 of License No. 37-07219-01 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in an application dated July 7, 1980; a letter dated August 4, 1981; a revised application attached to letter dated January 8, 1982, and letter dated February 16, 1982. Included with the revised application is the licensee's "Radiographic Manual".

Item 2.H of Section 5 (Training Program) of this manual requires that a radiography demonstrate his competence by passing an examination as specified in Attachment No. 2 of this section.

Contrary to the above, as of January 12, 1983, the radiographer employed by the licensee had not demonstrated his competence by passing the required examination.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Ampco - Pittsburgh Corporation is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including; (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8302160179 830201  
NMS LIC30  
37-07219-01 PDR