

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ][ ][ ][ ][ ][ ] ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S O S 2 0 0 0 0 0 0 0 0 0 0 0 0 0 ③ 4 1 1 1 1 ④ [ ][ ][ ][ ] ⑤

7 8 9 14 15 25 26 30 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 REPORT SOURCE L ⑥ 0 5 0 0 0 3 6 1 ⑦ 0 7 3 0 8 2 ⑧ 0 8 2 7 8 2 ⑨

7 8 60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 While in Mode 2, the condensate storage tank T-121 water level fell below the

0 3 Technical Specification 3.7.1.3 limit on 3 occasions. There was no

0 4 consequence to the public health and safety since there was no significant

0 6 decay heat in the core.

0 6

0 7

0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

H H ⑪ B ⑫ A ⑬ Z Z Z Z Z ⑭ Z ⑮ [ ][ ] ⑯

7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER EVENT YEAR 8 2 ⑰ SHUTDOWN METHOD Z ⑳ HOURS 0 0 0 0 ㉑ ATTACHMENT SUBMITTED N ㉒ NPR-4 FORM SUB. N ㉓ PRIME COMP. SUPPLIER Z ㉔ COMPONENT MANUFACTURER Z 9 9 9 ㉕

21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPR-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉖

1 0 Inadequate makeup water control to tank T-121 and a more restrictive than

1 1 necessary Technical Specification limit were the cause. Corrective actions include

1 2 a proposed Technical Specification change and a design change to install automatic

1 3 level control systems (expected to be installed prior to 100% power operation).

1 4

1 5 FACILITY STATUS B ㉘ % POWER 0 0 0 ㉙ OTHER STATUS NA ㉚ METHOD OF DISCOVERY A ㉛ DISCOVERY DESCRIPTION Operator observation ㉜

7 8 9 10 12 13 44 45 46

1 6 RELEASED OF RELEASE Z ㉝ AMOUNT OF ACTIVITY NA ㉞ LOCATION OF RELEASE NA ㉟

7 8 9 10 11 44 45 46

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 ㊱ TYPE Z ㊲ DESCRIPTION NA ㊳

7 8 9 11 12 13

1 8 PERSONNEL INJURIES NUMBER 0 0 0 ㊴ DESCRIPTION NA ㊵

7 8 9 11 12

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z ㊶ DESCRIPTION NA ㊷

7 8 9 10 43

8209080306 820827  
PDR ADOCK 05000361  
S PDR

PUBLICITY ISSUED N ㊸ DESCRIPTION NA ㊹

7 8 9 10 44

2 0

7 8 9 10

NAME OF PREPARER H. B. Ray PHONE 714/492-7700