

February 4, 1983

DJS Ltr. #83-120

James G. Keppler, Regional Administrator Regior III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reportable Occurrence Report #83-05/03L-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(d), abnormal degradation of systems other than those specified in ite | B.l.e. above designed to contain radioactive material resulting from the fission process.

John Warey

D. J. Scott

Station Superintendent Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement Pirector of Management Information & Program Control U.S. NRC, Document Management Branch File/NRC

FEB10 1983