



DESTROYED ORIGINAL

Certified By [Signature]

Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

August 23, 1982

Mr. R. C. Haynes
Regional Administrator
USNRC
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 82-080/01P
SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Saturday, August 21, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a service water leak was discovered inside the Containment Building, on No. 24 Containment Fan Coil Unit. The leak rate was approximately 1.0 gallons per minute, and the leak has been isolated.

An investigation is in progress, and a detailed report will be submitted in the time period specified by IE Bulletin 80-24.

Sincerely yours,

H. J. Midura

H. J. Midura
General Manager -
Salem Operations

RF:ks

CC. Distribution

8209130117 820823
PDR ADOCK 05000311
S PDR

The Bridge People

IE29