

Appendix

NOTICE OF VIOLATION

Harper-Grace Hospitals
Harper Division

License No. 21-04127-06
License No. 21-04127-08

As a result of the inspection conducted on August 25, 26 and 27, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 35.22(b)(1) requires monthly spot measurements on each teletherapy unit to include determination of timer accuracy.

Contrary to the above requirement, it was determined through statements by licensee representatives and the NRC inspectors review of spot check records that this condition is not being met. Specifically, timer accuracy on both of your teletherapy units was not determined in June 1982, May 1982, and March 1982. In addition, several spot checks in 1981 did not include timer accuracy.

This is a Severity Level IV violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

9/8/82
Dated _____

S.R. Lasuk
for D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

8209130213 820908
PDR ADOCK 07002942
C PDR