Appendix

NOTICE OF VIOLATION

Raltech Scientific Services, Inc.

License No. 48-11805-01

As a result of the inspection conducted on August 17, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 21 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in application dated June 30, 1978. Included in that application (Item 11a) is a requirement to calibrate survey meters every six months.

Contrary to the above requirement, on the day of the inspection, records indicated that one survey meter had not been calibrated within the six month interval. Specifically, your Eberline Model E-120, Serial No. 4016 survey meter was not calibrated from March 6, 1979 until February 4, 1982, a period greater than six months.

This is a Severity Level IV violation (Supplement VI).

The inspection showed that action had been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

Detad

D. G. Wiedeman, Chief

Materials Radiation Protection

Section 1