H. D. Thornburg, Chief, Field Support and Enforcement Branch Office of Inspection and Enforcement, Headquarters

UNIVERSITY OF CALIFORNIA AT LOS ANGELES (UCLA) DOCKET NO. 50-142

Enclosed is the subject report of the physical security inspection conducted on May 20, 1975.

With exception of the one infraction described in the report, the licensee is in compliance with the Security Plan. However, you will note in the report that two significant items were identified during the inspection which decrease the effectiveness of physical protection. These were discussed with licensee management who stated that they would "look into" possible solutions. Meanwhile, I feel that the matter should be referred to Reactor Licensing who could request the licensee to revise the Security Plan to include correction of the problem areas.

V. N. Rizzolo, Chief Materials and Plant Protection Branch

Enclosure: IE Inspection Report No. 50-142/7502 (IE-V-60)

cc w/encl.
IE Chief, M&PP
IE:HQ (4)
SG
RL
IE Files
NRC Central Files

8302220080 821230 PDR FDIA HIRSCH82-381 PDR

OFFICE	REGION V	REGION V	
	1		
SUPREME >	Schuster: ia	Rizzolo	
DATE >	6/ = 175	6/4/75	
From ASC. 118 - Fre C		670 13 15 414'5 1 41 40'8	