

APPENDIX A

University of California at Los Angeles  
Docket No. 50-142  
License No. R-71

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on July 29-30, 1976 it appears that one of your activities was not in full compliance with applicable NRC regulations and conditions of your license, as indicated below.

During a August 8, 1975 it was determined by the Laboratory Security Officer that one key was lost and one key was duplicated. It was determined July 30, 1976 that contrary to good security practices no corrective action had been taken.

This is a deficiency.

76-167  
Copy 12 of 13 copies  
1 pages

THIS DOCUMENT IS NOT TO BE  
REPRODUCED WITHOUT SPECIFIC  
APPROVAL OF IEV.