

WM 63/70



Department of Energy
Albuquerque Field Office
P.O. Box 5400
Albuquerque, New Mexico 87185-5400

MAR 24 1993

Mr. Ramon E. Hall
Director, Uranium Recovery
Field Office
Region IV
U.S. Nuclear Regulatory Commission
P.O. Box 25325
Denver, CO 80225



93 MAR 29 AM 11:15

URFO RECEIVED

Dear Mr. Hall:

Enclosed for your review and concurrence are two copies of Revision 1C to the Remedial Action Inspection Plan (RAIP) for the Mexican Hat, Utah, and Monument Valley, Arizona, Uranium Mill Tailings Remedial Action (UMTRA) Project site. We believe the RAIP adequately addresses inspection activities and is consistent with the following:

- o Remedial Action Plan
- o Design specifications
- o UMTRA Project quality assurance program requirements
- o U.S. Nuclear Regulatory Commission's Staff Technical Position Revision 2 on testing and inspection plans

Should you have any questions, please contact Milt Scoutaris of my staff at (505) 845-5630.

Sincerely,

Albert R. Chernoff
Project Manager
Uranium Mill Tailings Remedial Action
Project Office

Enclosure

cc:
See page 2

310024

OFFICIAL DOCKET COPY

WM-63
WM-70
NL14

93-0335

Mr. Ramon E. Hall

-2-

MAR 24 1993

cc w/enclosure:

F. Bosiljevac, UMTRA

R. Edge, UMTRA

M. Scoutaris, UMTRA

cc w/o enclosure:

NRC, Region IV

S. Hamp, UMTRA

J. McBee, TAC

G. Hauquitz, TAC

S. Martz, RAC