

APPENDIX A

The Regents of the University of California
School of Engineering
Los Angeles, California

Docket No. 50-142
License No. R-71

Notice of Deviation

Based on the results of the NRC inspection conducted on October 30-31, 1978, it appears that certain of your activities appeared to deviate from your internal security procedures or your commitment contained in your letter to Region V, USNRC, dated December 21, 1977, as indicated below.

1. The licensee stated in their letter to Region V, USNRC, dated December 21, 1977, Paragraph A.2, procedure is currently being formulated and will go into effect prior to January 20, 1978."

The inspector determined through interview of licensee personnel on October 31, 1978, that the licensee has not yet prepared or implemented procedure.

2. The licensee stated in their letter to Region V, USNRC, dated December 21, 1977, Paragraph B.1, "In addition, to ensure that all doors/latching mechanisms are in proper working order

Contrary to the above, the inspector determined through testing of the doors

in February, May and July 1978. At the time of the inspection, the locks had not yet been repaired.

S-F5-78-259
Copy 10 of 10 copies
1 pages

THIS DOCUMENT IS NOT TO BE
REPRODUCED WITHOUT SPECIFIC
APPROVAL OF IEV

U2 C5k 2790 INFORMATION