

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | A | S | 0 | 5 | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | R | P | O | R | T | S | O | U | R | C | E | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 1 | 7 | 0 | 8 | 0 | 1 | 8 | 2 | 8 | 0 | 8 | 3 | 1 | 8 | 2 | 9
8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 | White in Mode 2 Control Element Assembly (CEA) #57 slipped and dropped in excess
0 3 | of 7 inches (indicated position) in violation of Technical Specification 3.1.3.1.
0 4 | This event has no effect on public health and safety since they do not affect the
0 5 | ability of the CEA to insert into the core whenever required.
0 6 |
0 7 |
0 8 |

0 9 | SYSTEM CODE: I A 11 | CAUSE CODE: E 12 | CAUSE SUBCODE: B 13 | COMPONENT CODE: C R D R V E 14 | COMP. SUBCODE: Z 15 | VALVE SUBCODE: Z 16
17 | LER/RO REPORT NUMBER: 8 2 | EVENT YEAR: 8 2 | SEQUENTIAL REPORT NO.: 0 8 4 | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | REVISION NO.: 0
ACTION TAKEN: B 18 | FUTURE ACTION: Z 19 | EFFECT ON PLANT: Z 20 | SHUTDOWN METHOD: Z 21 | HOURS: 0 0 0 0 | ATTACHMENT SUBMITTED: N 23 | NPRD-4 FORM SUB.: N 24 | PRIME COMP. SUPPLIER: N 25 | COMPONENT MANUFACTURER: C 4 9 0 26

1 0 | The cause for the slippage is slow operation of the grippers which prevented one
1 1 | of the grippers (upper or lower) from making up to the CEA prior to the other
1 2 | gripper releasing. Corrective measures adopted included exercising the CEA and
1 3 | application of hydrazine to remove oxide deposits, and circuit modifications.
1 4 |

5 | FACILITY STATUS: B 28 | % POWER: 0 0 0 29 | OTHER STATUS: NA 30 | METHOD OF DISCOVERY: A 31 | DISCOVERY DESCRIPTION: Low Power Physics Testing 32

6 | ACTIVITY CONTENT RELEASED: Z 33 | AMOUNT OF ACTIVITY: NA 35 | LOCATION OF RELEASE: 36

7 | PERSONNEL EXPOSURES: NUMBER: 0 0 0 37 | TYPE: Z 38 | DESCRIPTION: NA 39

8 | PERSONNEL INJURIES: NUMBER: 0 0 0 40 | DESCRIPTION: NA 41

9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42 | DESCRIPTION: NA 43
8209140265 820831
PDR ADOCK 05000361
S PDR

0 | PUBLICITY ISSUED: N 44 | DESCRIPTION: NA 45

NAME OF PREPARER: H. B. Rav *HBRay/Nichols* PHONE: 714/492-7700