

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S O S 2 0 0 - 0 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5  
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 0 5 0 0 0 3 6 1 0 8 0 6 8 2 0 8 3 1 8 2 9  
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While in Mode 2 Control Element Assembly (CEA) #38 slipped and dropped in excess  
0 3 of 7 inches (indicated position) in violation of Technical Specification 3.1.3.1.  
0 4 This event has no effect on public health and safety since they do not affect the  
0 5 ability of the CEA to insert into the core whenever required.  
0 6  
0 7  
0 8

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE C R D R V E 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16  
8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO. 0 8 6 24 26 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32  
ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 4 9 0 26  
33 34 35 36 37 40 41 42 43 44 47

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause for the slippage is slow operation of the grippers which prevented one  
1 1 of the grippers (upper or lower) from making up to the CEA prior to the other  
1 2 gripper releasing. Corrective measures adopted included exercising the CEA and  
1 3 application of hydrazine to remove oxide deposits and circuit modifications.  
1 4

0 5 FACILITY STATUS B 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Low Power Physics Testing 32  
8 9 10 12 13 44 45 46 80  
0 6 RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
8 9 10 11 44 45 80  
0 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
8 9 10 11 12 13 44 45 80  
0 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
8 9 10 11 12 13 44 45 80  
0 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
8 9 10 11 12 13 44 45 80  
0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
8 9 10 11 12 13 44 45 80

B209140273 B20831  
PDR ADOCK 05000361  
S PDR

NAME OF PREPARER H. B. Rav HB Rav / NRC  
PHONE 714/492-7700

NRC USE ONLY