

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S O S 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

0 1 REPORT SOURCE L 0 5 0 0 0 3 6 1 0 8 0 7 8 2 0 8 3 1 8 2 9
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 While in Mode 2 Control Element Assembly (CEA) #77 slipped and dropped in excess
0 3 of 7 inches (indicated position) in violation of Technical Specification 3.1.3.1.
0 4 This event has no effect on public health and safety since they do not affect the
0 5 ability of the CEA to insert into the core whenever required.
0 6
0 7
0 8

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE C R D R I V E 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO. 0 9 2 24 26 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
ACTION TAKEN B 18 Z 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 4 9 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 The cause for the slippage is slow operation of the grippers which prevented one
1 1 of the grippers (upper or lower) from making up to the CEA prior to the other
1 2 gripper releasing. Corrective measures adopted included exercising the CEA and
1 3 application of hydrazine to remove oxide deposits, and circuit modifications.
1 4

5 FACILITY STATUS B 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Low Power Physics Testing 32
8 9 10 12 13 44 45 46
6 RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
8 9 10 11 44 45
7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
8 9 10 11 12 13
8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
8 9 10 11 12 13
9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
8 9 10 11 12 13
0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
8 9 10 11 12 13

8209140287 820831
PDR ADOCK 05000361
S PDR

NAME OF PREPARER H. B. Rav HB Rav / RCM
PHONE 714/492-7700

NRC USE ONLY