Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

August 20, 1982

TELEPHONE (714) 492 7700

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-206

24-Hour Confirmation Letter

Licensee Event Report No. 82-022

San Onofre Nuclear Generating Station, Unit 1

This letter provides written confirmation of a 24-hour report submitted in accordance with Section 6.9.2.a of Appendix A to Provisional Operating License DPR-13. The prompt notification of this occurrence was made to Mr. L. F. Miller, Resident Inspector for Unit 1, on August 19, 1982.

While in Mode 5 at approximately 5:30 a.m. on August 19, 1982 the North Salt Water Cooling Pump was secured due to mechanical problems. The South Salt Water Cooling Pump was already out of service for maintenance. Simultaneously with securing the North Salt Water Cooling Pump, the Auxiliary Salt Water Cooling Pump was placed in service to provide the necessary heat removal capability. Efforts were initiated to repair the North Salt Water Cooling Pump which resulted in its return to operable status at approximately 1:00 p.m. on August 19, 1982.

There was no adverse effect on public health or safety as a result of this event. A complete report of this matter together with Licensee Event Report No. 82-022 will be forwarded within 14 days.

Sincerely,

MBKay

cc: L. F. Miller (USNRC Resident Inspector, San Onofre Unit 1)

8209140309 820820 PDR ADDCK 05000206 S PDR