


YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367

February 6, 1983

Mr. R. C. Haynes, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Licensee Event Report 50-29/83-01-03L
Loss of Continuity Between MS-PS-21 (Main Steam Line
Pressure Switch) and TB-1.3 and TB-1.7

Dear Mr. Haynes:

In accordance with Technical Specifications, Section 6.9.4.b the
attached Licensee Event Report is hereby submitted.

Very truly yours,

Herbert A. Autio
Plant Superintendent

DAR/amt

Enclosures:

- cc: [30] Director, Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
- [3] Director, Officer of Management Information & Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
- [14] NSARC Chairman
- [1] Manager of Operational Quality Assurance (YAEC)
[1] Institute of Nuclear Power Operations (INPO)

830230124 830206
PDR ADOCK 05000029
S PDR

IE22