



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

MAR 28 1994

Docket: 150-00042
General License: 10 CFR 150.20
Texas License No. L03875

Fugro-McClelland (Southwest), Inc.
ATTN: Timothy G. Beckerle
Radiation Safety Officer
1107 West Gibson
Austin, Texas 78704

SUBJECT: NRC INSPECTION REPORT 150-00042/94-02

This refers to the routine, unannounced inspection conducted by Mr. Mark R. Shaffer of this office on February 23, 1994. The inspection included a review of activities authorized under General License pursuant to 10 CFR 150.20. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The licensee possesses an Agreement State license issued by the state of Texas which authorizes the use of moisture/density gauges for soils and materials testing at temporary jobsites throughout the state. Additionally, the licensee periodically performs licensed activities at locations within NRC jurisdiction under the authority of a general license pursuant to 10 CFR 150.20.

On January 12, 1994, the licensee submitted NRC Form 241 to this office to report proposed activities in NRC jurisdiction. Specifically, the licensee requested authorization to use portable gauging devices to conduct materials testing at several temporary jobsites in San Antonio and Brewster County, Texas. The jobsites identified on the NRC Form 241 are located on federal property and, therefore, are within NRC's regulatory authority.

As of the date of this inspection, the licensee had not used byproduct material within NRC jurisdiction during calendar year 1994. However, the inspector noted that the licensee had performed licensed activities on several occasions during 1993. These activities had also been approved by NRC under the authority of the general license pursuant to 10 CFR 150.20.

9404040023 940328
PDR STPRG ESQTX
PDR

LEO
11


Fugro-McClelland (Southwest). Inc. -2-

The licensee's records disclosed that leak tests and physical inventories of all sealed sources had been conducted at the required frequency. The licensee maintained certificates verifying the successful completion of the required training for each gauge user. Records of licensed activities were well maintained and adequate for the size and scope of the radiation safety program.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,


Samuel J. Collins, Director
Division of Radiation Safety
and Safeguards

cc:
Texas Radiation Control Program Director

bcc:
 DMB - Original (IE-07)
 LJCallan
 SJCollins
 RAScarano, DRSS/RIV
 LWCamper
 MMessier, OC/LFDCB (4503)
 *WLFisher
 *CLCain
 *MRShaffer
 *NMIB
 *MIS System
 *RIV Reciprocity File, DRSS (1)
 MCHernandez

 *W/IFS Form

*RIV:NMIB	C:NMIB <i>vac</i>	C:NMLB	D:DRSS	
MRShaffer	CLCain	WLFisher <i>WLF</i>	SJCollins	
03/ /94	03/9/94	03/16/94	03/25/94	

*Previously concurred

bcc:
DMB - Original (IE-07)
LJCallan
SJCcollins
RAScarano, DRSS/RIV
LWCamper
MMessier, OC/LFDCB (4503)
*WLFisher
*CLCain
*MRShaffer
*NMIB
*MIS System
*RIV Reciprocity File, DRSS (1)
MCHernandez

*W/IFS Form

*RIV:NMIB	C:NMIB <i>DLK</i>	C:NMLB	D:DRSS	
MRShaffer	CLCain	WLFisher <i>WLF</i>	SJCcollins	
03/ /94	03/9/94	03/16/94	03/25/94	

*Previously concurred