

Commonwealth Edison Dresden Nuclear Power Station R.R. #1 Morris, Illinois 60450 Telephone 815/942-2920

February 15, 1983

DJS Ltr. #83-165

James G. Keppler, Regional Administrator Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reportable Occurrence Report #83-11/01T-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.l.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment.

DVJ. Scott Station Superintendent Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of inspection & Enforcement
Director of inagement Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

8302230703 830215 PDR ADOCK 05000237 S PDR FEB 1 7 1983

TE22