

ENCLOSURE 1

NOTICE OF VIOLATION

GPU Nuclear Corporation  
Oyster Creek Nuclear Generating Station

Docket No. 50-219  
License No. DPR-16

During an NRC inspection conducted January 24, 1994 - March 7, 1994, two violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violations are listed below:

- A. 10 CFR 50, Appendix B, Criterion VI (Document Control), requires, in part, that measures shall be established to control the issuance of documents, such as instructions and procedures, affecting quality. These measures shall assure that documents, including changes are reviewed for adequacy.

Contrary to the above, on March 7, 1994, job order No. 47790, calibration of the "B" string main feedwater flow, was implemented without receiving an adequate technical review. The review that was performed failed to identify that main feedwater pump runout protection could not be bypassed and resulted in the closure of the "B" main feedwater regulating valve while operating at full power.

This is a severity level IV violation (Supplement I).

- B. 10 CFR 50, Appendix B, Criterion XVI (Corrective Action), requires, in part, that measures shall be established to assure that conditions adverse to quality are promptly identified and corrected.

Contrary to the above, the licensee failed to promptly identify and initiate corrective actions for conditions adverse to quality related to temporary strainers in plant systems. The need to identify and remove temporary strainers was initially identified in NRC Information Notice 85-96, which was closed by an administrative review. In August 1993, and in February 1994, the NRC identified three possible temporary strainers that had not been identified or corrected; one in the reactor building closed cooling water system, and two in the core spray system suction flowpaths from the condensate storage tank.

This is a severity level IV violation (Supplement I).

9404050133 940329  
PDR ADOCK 05000219  
Q PDR

**OFFICIAL RECORD COPY**

Pursuant to the provisions of 10 CFR 2.201, GPU Nuclear Corporation is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown consideration will be given to extending the response time.

Dated at King of Prussia, PA  
this 29th day of March 1994

**OFFICIAL RECORD COPY**