

## LICENSEE EVENT REPORT

**EXHIBIT A**

7	8	9	SYSTEM CODE C C (11)	CAUSE CODE E (12)	CAUSE SUBCODE B (13)	COMPONENT CODE H I T E X C H (14)	COMP NUMBER F (15)	VALVE SUBCODE Z (16)	80
7	8		9	10	11	12	13	14	
		(17) LER-HO REPORT NUMBER [8 2] 21 22	EVE-T YEAR [ ] 23	SEQUENTIAL REPORT NO. [012 8] 24 26	OCCURRENCE CODE [013] 27 29	REPORT TYPE [L] 30 31	REVISION NO [0] 32		
ACTION TAKEN X (18) 33		FUTURE ACTION X (19) 34	EFFECT ON PLANT A (20) 35	SHUTDOWN METHOD A (21) 36	HOURS [0 1 1 6 8] 37 38 39 40	ATTACHMENT SUBMITTED N (23) 41 42	NPRD-4 FORM SUR Y (23) 43	PRIME COMP SUPPLIER N (25) 44	COMPONENT MANUFACTURER C 4 9 0 (26) 45 46 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)									

10 The root cause of the leaking steam generator manway has not been determined.  
 11 The manway will be examined during the refueling outage to determine the cause and corrective actions.

7 8 9 10 11 12 13 44 45 46 80  
 ACTIVITY CONTENT RELEASED, OF RELEASE AMOUNT OF ACTIVITY 35  
 1 6 Z 33 Z 34 NA LOCATION OF RELEASE 36  
 7 8 9 10 11 44 45 46 80

PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (39)  
1 7 0 0 (37) Z (38) NA  
7 8 9 11 12 13

PERSONNEL INJURIES  
NUMBER 10 000 40 DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION (43)

1	9	Z (42) NA
---	---	-----------

1 8 9 10 PUBLICITY  
ISSUED DESCRIPTION 45 NRC USE ONLY  
20 Y 41 News Release, 8/23/82

7 8 9 10 68 69 70  
NAME OF PREPARER Patrick Rogers PHONE 501/964-3100  
8209240249 **820913**  
PDR ADOCK 05000368  
5 PDR