INIVERSIDAD DE PUERTO RICO, RECINTO DE CIENCIAS MEDICAS



G.P.O. BOX 5067 SAN JUAN, PUERTO RICO 00936-TEL, 758-2

12 22:84

FACULTAD DE CIENCIAS BIOSOCIALES Y ESCUELA GRADUADA DE SALUD PUBLICA
DEPARTAMENTO DE SALUD AMBIENTAL

June 5, 1989

Mr. Philip Stohr, Director Division of Radiation Safety and Safeguards U.S. Nuclear Regulatory Commission Atlanta, Georgia 30323

Dear Mr. Stohr:

Reference is made to your April 7, 1989 letter concerning the Picker dose calibrator (model 632-507) at the Division of Nuclear Medicine (Lic. 52-01946-07).

We want to advise you that the new calibrator arrived to our facilities and after all tests performed (linecrity, etc.) on it same was placed in service today.

The old calibrator is in the process of being returned to the Picker Corporation for evaluation of the assay error associated with 32 P. As soon as we have the evaluations performed we will communicate it to you.

Sincerely yours,

Heriofito forfes, Ph.D. Radiation Safety Officer

HT/stm

(8906190058) XA