

## MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

September 20, 1982

JAMES P. McGAUGHY, JR.

Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Fire Door Inoperability Reference: LER 82-057/03 L-0

AECM-82/414

On August 23, 1982, the supervisory alarm on the fire door separating the pipe chase and CRD pump area from the north stairwell went into alarm and would not clear. The continuous alarm was caused by a magnetic door switch which was out of adjustment. A Limiting Condition for Operation was entered pursuant to T.S.3.7.7. Attached is LER 82-057/03 L-0.

> Yours truly, LADON for J. P. H. Garshy

JPM:1m

Attachment

Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Document Control Desk (w/a) U.S. Nuclear Regulatory Commission Washington, D.C. 20555

OFFICIAL COPY