

1507/128

AUG 21 1990

Metric Medical Labs
ATTN: John Watkins
Vice President
of Operations
21705 Evergreen Road
Southfield, MI 48075

License No. 21-17741-01
Docket No. 030-13256

Gentlemen:

As a result of the inspection conducted on July 24, 1990, a NRC Form 591, SAFETY INSPECTION, is issued for License No. 21-17741-01. The enclosed form sets forth the violation noted. Please acknowledge receipt of this form by signing and dating in the appropriate space on all copies. You are requested to retain the original and return four signed and dated copies to this office within ten days.

I wish to express my appreciation for the cooperation extended to me during the inspection.

Sincerely,

~~Original~~ Signed By
James W. Patterson
J. W. Patterson
Radiation Specialist

Enclosure: NRC Form 591

0000

9009250059 900821
REG3 LIC30
21-17741-01 PDC

RIII *[Signature]*
Patterson/kjc
8/20/90

RIII *[Signature]*
GLS *[Signature]*
Caniano
8/21/90

11
IE07

SAFETY INSPECTION

1. LICENSEE Metric Medical Labs 21705 Evergreen Road Southfield, MI 48075		2. REGIONAL OFFICE U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD BLDG. #4 GLEN ELLYN, IL 60137	
3. DOCKET NUMBER(S) 030-13256	4. LICENSE NUMBER(S) 21-17741-01	5. DATE OF INSPECTION July 24, 1990	

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.
 - A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 20.203(b), (c), (d), (e) or 34.42.
 - B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
 - C. _____ sealed sources were not performed at the proper frequencies. 10 CFR _____ License Condition Number _____.
 - D. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
 - E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
 - F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
 - H. License Condition 15(A) references the application dated December 20, 1987, which requires that the survey instrument Model No. 2592 will be calibrated to a carbon-14 source monthly.
 - I. Contrary to the above, the licensee failed to perform survey meter calibrations to a carbon-14 source for the period May 14, 1985 through July 29, 1989.
 - J. _____
 - K. _____

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE	DATE	SIGNATURE - NRC INSPECTOR <i>fw Patterson</i>	DATE 8/14/90
----------------------	------	--	-----------------

9009250057 1P