In Reply Refer To: License: 42-26877-01 Docket: 030-29780/90-01

Anadrill, Inc.

ATTN: Mr. Guy Lombardo 200 Macco Boulevard Sugar Land, Texas 77478

## Gentlemen:

Enclosed for your signature is NRC Form 591 "Safety inspection." Please note the apparent violation which was observed during the July 30, 1990, temporary job site inspection of your NRC Byproduct Material License, and which was reported to you at the conclusion of the inspection. By signing the NRC Form 591, you agree to correct the violation within 30 days. Please keep the original for your records and return the remaining copies in the envelope provided. If you have any questions concerning this matter, please call me at (817) 860-8100.

Sincerely,

Original Signed By

Anthony D. Gaines Radiation Specialist

Enclosures:

1. NRC Form 591

Self-addressed envelope

cc:

Texas Radiation Control Program Director

bcc: √DMB - IE-07 RDMartin ABBeach WLFisher

\*CLCain \*Inspector \*MIS System

\*RIV Files (2)

MRodriguez, OC/LFDCB (MS 4503)
\*NMIS File \*

\*RSTS Operator (close report)

\*w/766


00443

RIV:NMIS ADCA C:NMISQKC ADGaines/ch CLCain 8/0/90 8/14/90

> 9009250137 900814 REG4 LIC30 42-26877-01 PDC

41100





TO: Distribution

FROM: Anadrill RSO

SUBJECT: Notice of Violation

DATE: 9/4/90

The attached Safety Inspection form and its notice of violation should immediately be addressed for all wellsite locations.

- All storage containers will have signs as per 10 CFR 20.203 (f)(2), (see attachment 3).
- Such signs will be removable or coverable as per 10 CFR 20.203 (f)(4), (see attachment 3).
- This letter and attachments 1, 2 and 3 will be posted as per 10 CFR 19.11 (a)(4), (b), (c), (d), (see attachment 4).
- The actions must be complete by 4-Oct-90.
- Posting in Scott, Louisiana and Sugar Land, Texas will commence upon receipt of this notice and cease on 4-Oct-90 or when complete compliance is achieved, (10 CFR 19.11 (e).

This is a more conservative interpretation of the regulations and as such the preferred standard of operation for Anadrill. Please attend to this matter as soon as possible and indicate in writing when the actions are accomplished.

Regards,

Guy Lombardo

GL/erh

Distribution:

M. Pawlowski

C. Kienitz

cc: D. Chilton

P. Kurkoski

K. Turner

cc Tony Gaines



## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76011

AUS 14 1000

In Reply Refer To: License: 42-26877-01 Docket: 030-29780/90-01

Anadrill, Inc.

ATTN: Mr. Guy Lombardo 200 Macco Boulevard Sugar Laid, Texas 77478

Gentleren:

Enclosed for your signature is NRC Form 591, "Safety Inspection." Please note the apparent violation which was observed during the July 30, 1990, temporary job site inspection of your NRC Byproduct Material License, and which was reported to you at the conclusion of the inspection. By signing the NRC Form 591, you agree to correct the violation within 30 days. Please keep the original for your records and return the remaining copies in the envelope provided. If you have any questions concerning this matter, please call me at (817) 860-8100.

Sincerely,

Anthony D) Gaines
Radiation Specialist

Enclosures:

1. NRC Form 591

2. Self-addressed envelope

cc:

Texas Radiation Control Program Director

Attachment 1