

APPENDIX A

NOTICE OF VIOLATION

Entergy Operations, Inc.
Waterford Steam Electric Station

Docket: 50-382
Operating License: NPF-38

During an NRC inspection conducted August 20-24, 1990, a violation of NRC requirements was identified. The violation involved the failure to qualify tape splices used in instrument circuits subject to harsh environments. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990) (Enforcement Policy), the violation is listed below:

10 CFR 50.49(j) requires, in part, that documentation must be maintained to permit verification that each item of electric equipment important to safety covered by this section: (1) is qualified for its application; and (2) meets the specified performance requirements when subjected to the conditions predicted to be present when the equipment must perform its function.

Contrary to the above, from November 30, 1985, to August 24, 1990, the licensee failed to have documentation to demonstrate the qualification of tape splices used in instrument circuits that would be subjected to harsh environments.

This is a Severity Level IV violation. (Supplement 1)(382/9016-02)

Based on the evaluation of the licensee's submittal of May 21, 1990, regarding this violation, and the planned corrective actions contained therein, no response to this violation is required.

Dated at Arlington, Texas,
this 18th day of September 1990

9009250276 900918
PDR ADDCK 05000382
Q PDC