

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

September 17, 1982

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

82 SEP 24 11:01
NRC REGION II
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-68. This report concerns T.S.3.7.11, "All fire barrier penetrations (including cable penetration barriers, fire doors and fire dampers) in fire zone boundaries protecting safety-related areas, shall be functional". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tucker / BT

Hal B. Tucker

HBT:PBN:jfw
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
320 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station

8209300219 820917
PDR ADOCK 05000369
S PDR

OFFICIAL COPY
1022