U. S. NUCLEAR REGULATORY COMMISSION

(1-11)	LICENSEE EVENT REPORT Attachment to AECM-82/419 Page 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 STOCAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 8 2 4 8 2 8 0 9 2 2 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	The fire detection zone covering the fuel handling area and ventilation equipment area
0 3	went into alarm and reset several times. Operations investigated the area and found
0 4	no sign of fire or smoke. The alarm was de-activated and declared inoperable. A
0 5	fire watch was established in accordance with T.S.3.3.7.9. There was no danger to
0 6	the health and safety of the public.
0 7	
0878	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9 8	CODE SUBCODE S
	17 REPORT NUMBER 2 23 24 26 27 28 29 30 31 32 NO.
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER H 2 6 0 26 Z 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 V 24 42 43 43 45 H 2 6 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	Investigation showed the alarm was clear and the alarm reset. The alarm can only be
11	attributed to system noise or dust. The zone was returned to service the same day.
1 2	Repetitive occurrences of this nature will be tracked and reviewed for further
1 3	corrective action. This is intended as a final report.
14	80
1 5	G 28 0 0 0 0 29 NA Alarmed Condition 30 B0 Alarmed Condition 30 B0 Alarmed Condition B0
	CCTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA N
1 7 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA N
18	PERSONNEL INJURIES NUMBER 0 0 0 0 0 0 0 0 NA NA 9 11 12 NA
1 9	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 9 10 8209300259 820922 80
20	PUBLICITY DESCRIPTION 45 PDR ADOCK 05000416 NRC USE ONLY N 44 SSUED DESCRIPTION 45 NA PDR NA
	NAME OF PREPARER Original Signed by Ray Patterson PHONE