



September 21, 1982

Log No. K82-1378  
FILE: RR 2 (NP-33-82-45)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-040  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: August 23, 1982

Enclosed are three copies of Licensee Event Report 82-040 with a supplemental information sheet, which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

A handwritten signature in cursive script that reads "Terry D. Murray".

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/lmr  
Enclosure

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Walt Rogers  
NRC Resident Inspector  
Encl: 1 copy

8209300339 820921  
PDR ADOCK 05000346  
S PDR

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

SEP 24 1982

IE22