

EDISON DRIVE • AUGUSTA, MAINE 04336 • (207) 622-4868

September 21, 1990 MN-90-93 SEN-90-270

UNITED STATES NUCLEAR REGULATORY COMMISSION

Attention: Document Control Desk

Washington, DC 20055

References:

a) License No. DPR-36 (Docket No. 50-309)

(b) USNRC Letter to Maine Yankee dated October 27, 1989, Inspection No. 50-309/89-81

(c, M. ine Yankee Letter to USNRC dated December 1, 1989 (MN-89-145), Response to Inspection Report No. 50-309/89-81

(d) Maine Yankee Letter to USNRC dated December 29, 1989 (MN-89-157), Response to Inspection Report No. 50-309/89-81

(e) USNRC Letter to Maine Yankee dated May 8, 1990 - Evaluation Report No. 50-309/90-01 (OLRQ)

Subject: Emergency Procedures Inspection Follow-Up Response

Gentlemen:

With References (c) and (d), Maine Yankee indicated we were addressing the open items raised during the NRC's inspection of our emergency operation procedures, and that we intended to provide a followup response for one item (89-81-10). We have communicated our actions to resolve 89-81-10 to members of your staff and the item was closed by Reference (e).

Should you have any questions on this matter, please contact us.

Very truly yours,

S. E. Nichols

SENILL

Licensing Section Head

RCC:SJJ

c: Mr. Charles S. Marschall

Mr. Eric J. Leeds Mr. Thomas T. Martin

> 9010010172 900921 PDA ADOCK 05000309 Q PDC