SAFETY INSPECTION

1. LICENSEE

Pan American World Airways, Inc. Aerospace Services Division Pan Am 9, OMEHS Kennedy Space Center, Florida 32899

U. S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta ST., N. W. Atlahta, Georgáa 30303

30-3974

4. LICENSE NUMBER(S)

09-05634-01

5. DATE OF INSPECTION

4-1 = 4-2-82

Licenson

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

1. Within the scope of this inspection, no violations were observed.

- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

was not properly posted to indicate the presence of a ___ __ 10 CFR 20.203(b), (c), (d), (e) or 34.42.

B. Containers located in . were not properly It belied to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2),

of sealed sources were not performed at the proper frequencies. 10 CFR License Condition Number _

D. Records of were not properly maintained. or License Condition Number _

E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

F. Reports or notifications of were not made in accordance or License Condition Number _ with 10 CFR

hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC

8210010034 820901 NMS LIC30 09-05634-01

PDR

SIGNATURE - LICENSEE

10 CFR 2 201		SAFETY INSP	ECTION	
1. LICENSEE	Pan American World Airways, Inc. Aerospace Services Division Pan Am 9, OMEHS Kennedy Space Center, Florida 32899		REGIONAL OFFICE U. S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta ST., N. W. Atlahta, Georgán 30303	
3. DOCKET NU	IMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION	
	30-3974	09-05634-01	4-1 = 9-2-82	
Regulatory Com and representation 1. Within the 2. The inspec	nmissions (NRC) rules and req ive records, interviews, with p ne scope of this inspection, no	gulations and the conditions of your lice personnel, and observations by the inspec- violations were observed.	they relate to radiation safety and to compliance with the Nucleonse. The inspection consisted of selective examinations of processor. The findings as a result of this inspection are as follows: Identified during the last inspection. We have no further question	edures
		activities, as checked below, were in vio		
	ainers located ined to indicate the presence of	radioactive material, 10 CFR 20,203(f)	was not properly posted to indicate the page 10 CFR 20.203(b), (c), (d), (e) or were not page 11), or (f)(2).	r 34.42.
c			of sealed sources were not performed at the	proper
freque	encies. 10 CFR		License Condition Number	
D. Recor			were not properly main	ntained.
		or Lic	19.11. were not made in acc	ordance
	10 CFR	or Lie	ense Condition Number	
Пн				
J				
Пк				

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC. 8210010034 820901

NMS LIC30

09-05634-01 PDR

SIGNATURE - LICENSEE

DATE

SIGNATURE - NECTNSPECTOR