(7₂91) 10 CFR 8.201

SAFETY INSPECTION

			Page 1 of
1. UCENSEE University of Virginia Schooled Engineering and Ap Reactor Facility Charlottesville, VA 22901	plied Science	101 MA	N II ICLEAR REGULATORY COMMISSION IRIETTA STREET NW SUITE 2900 TA GA 30323
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION
080-05738	SUD-657		1/25/93
Flegulatory Commission (NRC) rules and regulatory	lations and the conditions iews with personnel, and c	s of your license. The inspendence of your license. The inspendence of	to radiation safety and to compliance with the Nuclear spection consisted of selective examinations of actor. The findings as a result of this inspection are as
questions on those actions at this ti	me.		during the last inspection. We have no further
NOTICE OF VIOLATION, which is re	quired to be posted in acc	cordance with 10 CFR 19	
house			was not properly posted to
indicate the presence of a			10 CFR 20.203(b),(c),(d),(e) or 34.42.
B			of sealed sources were not
performed at the proper frequ	uencies. 10 CFR	or License	Condition Number
C. Records of			were not properly maintained.
10 CFR	or License Condition N	umber	
D. Documents were not properly	posted or otherwise mad	e available. 10 CFR 19.1	
E. Reports or notification of			were not made in accordance with
Amend	10 CFR or License Condition Number		
9404080203 9301 PDR ADDCK 0400			
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	described by me to the li- made in accordance with	nspector will be taken to the requirements of 10	correct the violations identified in the items checked CFR 2.201. No further response will be submitted.
SIGNATURE - LICENSES 080	DATE	SIGNATURE - NAC INS	PECTOR DATE