NAC FORM 501 PART 1 CLOSE COT SURVEY U.S. NUCLEAR REGULATORY COMMISSION

10 CFR 2.201		SAFETY	INSPECTION	Page 1 of /
1. LICENSEE Whitby Research, Incorporated P.O. Box 27426 Richmind, Virginia 23261-7426		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323		
		4 LICENSE NUMBER(6 45-25111-01	5)	5. DATE OF INSPECTION 2 /18/94
Regulatory Corprocedures and fellows: 1. Within 2. The inquest 3. Durin	mmission (NRC) rules and re d representative records, inte in the scope of this inspection inspector also verified the ate tions on those actions at this	gulations and the condition riviews with personnel, and no violations were observings you have taken to correctime.	s of your license. The in observations by the insported of the violations identified below or attached, were	to radiation safety and to compliance with the Nuclei spection consisted of selective examinations of ector. The findings as a result of this inspection are a during the last inspection. We have no further in violation of NRC requirements. This form is a 3.11.
A 8	indicate the presence of a			of sealed sources were not
c.	Performed at the proper free Flecords of	or License Condition N	lumber	were not properly maintained.
E. F.		or License Condition N		were not made in accordance with
Thereby state th	nas, within 30 days, the actio	ns described by me to the	inspector will be taken to	correct the violations identified in the items checked

above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE -- NRC INSPECTOR

9404110080 940218 PDR ADDCK 03031858 C PDR