NRC FORM 591 PART 1 (7-91)

SAFETY INSPECTION

U.S. NUCLEAR REGULATORY COMMISSION

			Page 1 of	
1. LICENSEE		2. RE	GIONAL OFFICE	
Greet Lakes Testing, Inc. 3171 Grees St. Green Bay, WI 54304			REGION III U S NUCLEAR REGULATORY COMMISSION 799 ROOSEVELT ROAD GLEN ELLYN IL 60137	
B. DOCKET NU	JMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION	
03(+3312)		48-26484-01	3/15/94	
Regulatory Con procedures and allows:	mmission (NRC) rules and reg d representative records, inter	ulations and the conditions of yo views with personnel, and observ	ense as they relate to radiation safety and to compliance with the Nucleur license. The inspection consisted of selective examinations of ations by the inspector. The findings as a result of this inspection are	
2. The in	n the scope of this inspection inspector also verified the step tions on those actions at this t	s you have taken to correct the v	iolations identified during the last inspection. We have no further	
		our activities, as described below equired to be posted in accordan	or attached, were in violation of NRC requirements. This form is a see with 10 CFR 19.11.	
A.			was not properly posted to	
	indicate the presence of a _		. 10 CFR 20.203(b),(c),(d),(e) or 34.42	
8.			of sealed sources were not	
	performed at the proper free	quencies. 10 CFR	or License Condition Number	
C.	Records of		were not properly maintained.	
-	10 CFR	or License Condition Number		
D.	Documents were not proper	ly posted or otherwise made avail	lable. 10 CFR 19.11.	
E.	Reports or notification of		were not made in accordance with	
	10 CFR	or License Condition Number		
F.				

SIGNATURE - LICENSEE

SIGNATURE -- NRC INSPECTOR

9404110103 940330 PDR ADOCK 03033120 C PDR

Donald R. Hellon

3-27-94