2.81)			U.S. NUCLEAR REGULATORY COMMISSION
) CFR 2 201	SAFETY II	NSPECTION	G(1) II, 6/83
Benjamin F. Shaw Company Old Airport Site Laurens, SC 29360		U. S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta Street, N. W. Atlanta, GA 30303	
30-06369	39-13318-01		Sept 17., 1982
egulatory Commissions (NRC) rules and in differentiative records, interviews, with 1. Within the scope of this inspection,	regulations and the conditions of you on personnel, and observations by the no violations were observed.	ur license. The inspect inspector. The finding	liation safety and to compliance with the Nuclear ion consisted of selective examinations of procedures as a result of this inspection are as follows:  the last inspection. We have no further questions on
	ur activities, as checked below, were	accordance with 10 CF	R 19.11.
B. Containers located in	of radioactive material. 10 CFR 20.	203(f)(1), or (f)(2).	were not proper
frequencies. 10 CFR			of sealed sources were not performed at the proper Condition Number
			were not properly maintained
	osted or otherwise made available. 1		
I I Heports or politications of			/umberwere not made in accordance
with 10 CFR			
with 10 CFR			
with 10 CFR			

8210010319 820917 NMS LIC30 39-13318-01 PDR

DATE

SIGNATURE - NRC INSPECTOR

TE07