

MAY 21 1982

Carolina Power and Light Company
ATTN: Mr. J. A. Jones, Senior Executive
Vice President and Chief
Operating Officer
411 Fayetteville Street
Raleigh, NC 27602

Gentlemen:

Subject: Report Nos. 50-325/82-15, 50-324/82-15, 50-261/82-17, 50-400/82-14 and
50-401/82-14; Systematic Assessment of Licensee Performance (SALP)
Board Reports for your Brunswick, Robinson and Harris Plants

The NRC SALP Board has evaluated the performance of the subject facilities for the period July 1, 1980 through December 31, 1981. The results of this meeting are documented in the enclosed SALP Board Report. This evaluation will be discussed with you at your offices in Raleigh on May 28, 1982.

The performance of your Brunswick and Robinson facilities was evaluated in the following functional areas: plant operations; refueling operations; maintenance; surveillance and inservice testing; personnel, training and plant procedures; fire protection and housekeeping; design changes and modifications; radiation protection, radioactive waste management and transportation; environmental protection, emergency preparedness; security and safeguards; audits, reviews, and committee activities; QA; administrative, and records; and corrective actions and reporting.

The performance of your Harris facility was evaluated in the following functional areas: quality assurance; site preparation and foundation; containment structure; safety-related structures; piping and hangers; safety-related components; electrical systems; fire protection; corrective actions and reporting; procurement; design and design changes; and training.

The SALP Board evaluation process consists of categorizing performance in each functional area. The categories which we have used to evaluate the performance of your facilities are defined in section II of the enclosed SALP Board report. As you are aware, the NRC has changed the policy for the conduct of the SALP program based on our experiences and the recently implemented reorganization which emphasizes the regionalization of the NRC staff. This report is the product of the revised policy. It was prepared in the transition period between the old and the new SALP programs and accordingly is different from last years' SALP Report and will be different from future SALP Reports.

Any comments which you may have concerning our evaluation of the performance of your facilities should be submitted to this office within twenty days of the date of the meeting in Raleigh.

MAY 2 1982

Carolina Power and Light Company


2

Your comments, if any, and the SALP Board Report, will both appear as enclosures to the Region II Administrator's letter which issues the SALP Report as an NRC Report. In addition to the issuance of the report, this letter will, if appropriate, state the NRC position on matters relating to the status of your safety programs.

Comments which you may submit at your option, are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,



R. C. Lewis, Director
Division of Project and
Resident Programs
Region II SALP Board Chairman

Enclosure:
SALP Board Report for Carolina Power
and Light Company

cc w/encl:
C. R. Dietz, Plant Manager
R. B. Starkey, Jr., Plant General Manager
R. M. Parsons, Project General Manager

bcc w/encl:
NRC Resident Inspector

RII
DM
TMacArthur:ejw
5/21/82

RII
DL
DSPrice
5/21/82

RII
RL
RLewis
5/ /82

RII
JA
JA01shinski
5/21/82