APR 5 1994

Docket No. 50-271

Mr. Donald A. Reid Vice President, Operations Vermont Yankee Nuclear Power Corporation RD 5, Box 169 Ferry Road Brattleboro, Vermont 05301

Dear Mr. Reid:

## SUBJECT: VERMONT YANKEE INSPECTION REPORT NO. 50-271/94-02

This letter transmits the findings of a safety inspection of your Vermont Yankee Nuclear Power Plant licensed operator regualification training program. The inspection was conducted by Mr. D. Florek and Mr. A. Burritt of this office from February 14 through March 2, 1994. At the conclusion of the inspection, Mr. Burritt held discussions of the inspection findings with members of your staff.

The proper implementation of the NRC-approved licensed operator regualification training program is strongly related to the continued safe operation of the facility. This particular inspection was conducted using NRC Temporary Instruction (TI) 2515/117, "Licensed Operator Regualification Program Evaluation." This Instruction had been developed because of the rulemaking that deleted the requirement that the NRC staff examine each licensed operator for the purpose of license renewal. The purpose of this Instruction is to evaluate the acceptability of your licensed operator regualification training program with respect to Part 55 regulations through a performance-based inspection in lieu of an NRC staff regualification examination of licensed operators.

While the results of this inspection determined that the Vermont Yankee regualification training program was being implemented in accordance with the requirements of 10 CFR Of And: New Pert Hour 55.59 in the areas reviewed, several notewo thy programmatic weaknesses were identifed, which negatively impact the effectiveness of your requalification training program. Programmatic weaknesses involved: (1) recurrent crew performance deficiencies in the area of crew command and control, communications, and adherence to Emergency Operating Procedures (EOPs); (2) relatively low level of knowledge being tested in parts of the written and signalator tests; and (3) poor documentation of details related to performance deficiencies and remediation training (section 3).

OFFICIAL RECORD COPY A: VY9402. INS

20048 940405 ADOCK 0500027

## Mr. Donald A. Reid

Of most importance were the repetitive problems with crew command and control, communication, and emergency operating procedural adherence that have been identified by your staff, as well as by NRC staff. We understand that you intend to meet with us on April 25, 1994, to present your staff's assessment of the requalification training program effectiveness and discuss the generic observations and corrective actions. We believe that the meeting would be valuable to both staffs if it also addressed those actions to correct the weaknesses identified in this report. We, therefore, request that your presentation include an assessment of the repetitive problems observed and the other findings contained in the enclosed inspection report.

No response to this letter is required. In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room. Should you have any questions regarding this inspection, please contact Mr. Richard Conte at (610) 337-5210.

Sincerely,

Triginal Signed Dit.

James T. Wiggins, Deputy Director Division of Reactor Safety

Enclosure: NRC Region I Inspection Report 50-271/94-02

OFFICIAL RECORD COPY A:VY9402.INS

## Mr. Donald A. Reid

cc w/encl:

R. Wanczyk, Plant Manager J. Thayer, Vice President, Yankee Atomic Electric Company L. Tremblay, Senior Licensing Engineer, Yankee Atomic Electric Company J. Gilroy, Director, Vermont Public Interest Research Group, Inc. D. Tefft, Administrator, Bureau of Radiological Health, State of New Hampshire Chief, Safety Unit, Office of the Attorney General, Commonwealth of Massachusetts R. Gad, Esquire G. Bisbee, Esquire R. Sedano, Vermont Department of Public Service T. Rapone, Massachusetts Executive Office of Public Safety Public Document Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center (NSIC) K. Abraham, PAO (2) NRC Resident Inspector State of New Hampshire, SLO Designee State of Vermont, SLO Designee Commonwealth of Massachusetts, SLO Designee

bcc w/encl: Region I Docket Room (with concurrences) E. Kelly, DRP J. Shedlosky, DRP M. Oprendek, DRP

bcc w/encl (VIA E-MAIL): V. McCree, OEDO D. Dorman, NRR W. Butler, NRR M. Shannon, ILPB

## (VIA E-MAIL AND NO ATTACHMENTS):

R. Conte, DRS A. Burritt, DRS D. Florek, DRS

Independent Review By: RI:DRS RI:DRS RI:DRS RI:DRS Burritt/ajk/dmg Plopek Williams OND thet AM 03/16/94 AD104 03/15/94 -03/5794 OY

OFFICIAL RECORD COPY A : VY9402.INS