Form 601	U.S. NUCLEAR REGULATORY COMMISSION	
(1281) 10 CFR 2 201	SAFETY INSPECTION	90-01
1 LICENSEE	2 REGIONAL OFFICE	
Lee M Machemer & SON, INC. REGION I 1431 South Fourth Street, Real 175 Allendale Rd. PA 15day		
Allentown, Pennsylvania 18103 Hing of Prussia, PA 19406 3 DOCKET NUMBER(S) [5 DATE OF INSPECTION		
030-22127	37.20824-01	Hugust 28, 1110
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:  1 Within the scope of this inspection, no violations were observed.  2 The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on		
	ties, as checked below, were in violation of NRC requ h is required to be posted in accordance with 10 CFR	
^_		was not properly posted to indicate the presence 10 CFR 20.203(b), (c), (d), (e) or 34.42
B. Containers located in	active material. 10 CFR 20.203(f)(1), or (f)(2).	of sealed sources were not performed at the proper andition Number
D. Records of		
F. Reports or notifications of with 10 CFR	otherwise made available. 10 CFR 19,11.  or License Condition Nur	were not made in accordance
MH Transportation of radioactive material not conducted in		
Accordance with the provisions of 10 CFR Fartite		
Di Certificate of training for a user was not maintained		
7		
DESIGNATED ORIGINAL		
Certified By:		nal to Region I
L.K	7.8	to Region 1
		AUG. AUG. AUG. AUG. AUG. AUG. AUG. AUG.
	probable by me to the inspector will be taken to correct to produce with the requirements of 10 CFR 2.201. No DATE SIGNATUR	
9010120022 900828 REG1 L1030 37-20824-01 PDC		