

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
L I S 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
R P T S O C K E T N U M B E R E V E N T D A T E R E P O R T D A T E
L 0 5 0 0 0 3 0 4 0 8 2 7 8 2 0 9 2 4 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 | During pwr op while running 2A turbine-driven Aux FW Pump (AFWP),
0 3 | flow was observed on the other discharge header associated with
0 4 | the 2 motor-driven AFWP. The 2 cross-tie valves between the 2
0 5 | AFWP discharge headers were found open, resulting in a reduction
0 6 | in the degree of redundancy of the AFW Systems, reportable per
0 7 | TS 6.6.(b).3. The 2A and 2C AFWP were operable. 2B AFWP was
0 8 | available, but not proved operable by testing.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
S H A A V A L V E X F D
L E P / R O R E P O R T N U M B E R E V E N T Y E A R S E Q U E N T I A L R E P O R T N O . O C C U R R E N C E C O D E R E P O R T T Y P E R E V I S I O N N O .
A C T I O N T A K E N F U T U R E A C T I O N E F F E C T O N P L A N T S H U T D O W N M E T H O D H O U R S A T T A C H M E N T S U B M I T T E D N P R O - 4 F O R M S U B . P R I M E C O M P . S U P P L I E R C O M P O N E N T M A N U F A C T U R E R
X G Z Z 0 1 0 0 0 0 N N A P 3 0 1 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 | The cross-tie vlvs between the 2 AFWP discharge headers were
1 1 | mistakenly opened because the procedure for lining up 2B AFWP
1 2 | (in preparation to returning the pump to service) was improperly
1 3 | followed. These vlvs were immediately closed and 2B AFWP was
1 4 | successfully tested the same day. Evaluation indicates the
1 5 | procedure needs clarification and this will be done.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
E 1 0 0 NA B Operator Observation
F A C I L I T Y S T A T U S P O W E R O T H E R S T A T U S M E T H O D O F D I S C O V E R Y D I S C O V E R Y D E S C R I P T I O N

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
Z Z NA NA
A C T I V I T Y R E L E A S E D C O N T E N T A M O U N T O F A C T I V I T Y L O C A T I O N O F R E L E A S E

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 0 0 Z NA
P E R S O N N E L E X P O S U R E S N U M B E R T Y P E D E S C R I P T I O N

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 0 0 NA
P E R S O N N E L I N J U R I E S N U M B E R D E S C R I P T I O N

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
Z NA
L O S S O F O R D A M A G E T O F A C I L I T Y T Y P E D E S C R I P T I O N

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
N NA
P U B L I C I T Y I S S U E D D E S C R I P T I O N

NAME OF PREPARER Gene Johnson

PHONE: 312-746-2084 X314

8210040121 820924
PDR ADDCK 05000304
S PDR