

Appendix

NOTICE OF VIOLATION

Illinois Department of Nuclear Safety

License No. 12-20084-01

As a result of the inspection conducted on August 25 and 26, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 10 states: licensed material listed in Subitem 6.A. of the license shall be used only at the licensee's facilities at 535 West Jefferson Street, Springfield, IL and at temporary job sites of the licensee throughout the State of Illinois.

Contrary to this requirement, as of the dates of this inspection, sealed sources as specified by Subitem 6.A. of the license were being permanently stored and used at 525 West Jefferson Street, Springfield, Illinois and not at the address delineated in the license.

This is a Severity Level V violation (Supplement VI).

2. 10 CFR 30.51(a) states: each person who receives byproduct material shall keep records showing the receipt, transfer, and disposal of such byproduct material.


Contrary to this requirement, as of the dates of this inspection, records of byproduct material receipts were not available for a nominal 150 microcurie sealed source of Cs-137 (No. 3) transferred from the State of Illinois Region III site between November 1981 and February 1982.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

9-23-82

Dated



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1