



**Wisconsin
Electric**
POWER COMPANY

231 W. Michigan, P.O. Box 2046, Milwaukee, WI 53201-2046

(414) 221-2345

April 5, 1994

"PL 94-0136

Document Control Desk
U.S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, DC 20555

Gentlemen:

DOCKET# 50-266 AND 50-301
COMPLETION OF ACTIONS IN RESPONSE TO NRC BULLETIN 88-10,
"NONCONFORMING MOLDED-CASE CIRCUIT BREAKERS"
POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

NRC Bulletin 88-10, dated November 22, 1988, requested that licensees take actions to ensure that molded case circuit breakers that cannot be verifiably traced to the circuit breaker manufacturer are capable of performing their safety functions. In a letter, dated November 5, 1990, we provided you with an update on the actions being taken to address the bulletin's recommendations. We stated that the remaining nontraceable circuit breakers in inverters 1DY03, 2DY03, DY0C, 1DY04, 2DY04, and DY0D would be replaced with new circuit breakers as soon as acceptable replacement circuit breakers could be obtained.

This letter is being submitted to inform you that all of the nontraceable circuit breakers identified above have been replaced and associated post-installation testing has been satisfactorily completed. The final breaker replacements were made in inverter 2DY04 and were completed on March 4, 1994. These actions complete all of our commitments made in response to NRC Bulletin 88-10.

Please contact us if there are any questions.

Sincerely,

Gary M. Krieser
Manager
Industry and Regulatory Services

cc: NRC Regional Administrator, Region III
NRC Resident Inspector

9404140149 940408
PDR ADDCK 05000266
Q PDR

JEH 1/0