LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C A S 0 S 2 2 0 0 - 0 0 0 0 - 0 0
CON'T	REPORT L 6 0 5 0 0 0 0 3 6 1 0 0 8 2 9 8 2 8 0 8 2 4 8 2 9 8 12 8 0 8 12 4 8 12 9 18 12 9 18 12 19 18
0 2	While in Mode 3, the condensate storage tank T-121 water level fell below the
0 3	Technical Specification 3.7 1.3 limit. There was no consequence to the public
0 4	health and safety since there was no significant decay heat in the core.
0 5	
06	
0 7	
08	EVERTE
0 9	CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBC
**	TO REPORT NUMBER SEQUENTIAL REPORT NO. CODE TYPE NO.
	ACTION FUTURE ON PLANT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ON PLANT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER ON PLANT SUBMITTED FORM SUB. SUPPLIER SUBMITTED FORM SUB. SUBMITTED FORM SUBMITTED FORM SUBMITTED FORM SUBMITTED FORM SUB. SUBMITTED FORM SUBMITTED FORM SUBMITTED FORM SUBMITTED FORM SUBMITTED FORM SUBMI
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	Inadequate makeup water control to tank T-121 and a more restrictive than necessary
111	Technical Specification limit were the cause. Corrective actions include a proposed
1 2	Technical Specification change and a design change to install automatic level control
13	systems (expected to be installed prior to 100% power operation).
1 4	
	STATUS STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA 31 Operator Observation
	CTIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 1
118	PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41 NA
1 9	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA S PDR ADDCK 05000361 PDR ADDCK 05000361
, 8	9 10 PUBLICITY 80 NRC USE ONLY
7 8	NA NA NA
	NAME OF PREPARER H. B. Ray 1 7 (MM) 1 14/492-7700