	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C   A   S   O   S   Z   Q   O   O   O   O   O   O   O   O   O
O 1 8	REPORT L 6 0 5 0 0 0 3 6 1 0 0 9 8 2 8 0 8 12 8 0 18 12 4 18 12 9  EVENT DESCRIPTION AND REPORT OF SCHOOLS (8)
0 2	While in Mode 2, the condensate storage tank T-121 water level fell below the
0 3	Technical Specification 3.7.1.3 limit. There was no consequence to the public
0 4	health and safety since there was no significant decay heat in the core.
0 5	
06	
0 7	
08	9
0 9	CODE SUBCODE S
=	TO REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
•	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER SUBPLIER SUBPLIER SUPPLIER SUBPLIER SUPPLIER
10	Inadequate makeup was ar control to tank T-121 and a more restrictive than necessary
111	Technical Specification limit were the cause. Corrective actions include a proposed
1 2	Technical Specification change and a design change to install automatic level control
1 3	systems (expected to be installed prior to 100% power operation).
	9
1 5	STATUS POWER OTHER STATUS (30) DISCOVERY DESCRIPTION (32)  A (31) Operator Observation
A	PERSONNEL EXPOSURES  10 11 12 13 44 45 46  LOCATION OF RELEASE 36  80  10 11 PERSONNEL EXPOSURES
1 7	9 PERSONNEL INJURIES 13 BO
1 8	NUMBER OF TO SECULTA OF THE PROPERTY OF THE PR
1 9	TYPE DESCRIPTION (43) NA  10
2 0	PUBLICITY   8210050050 820924   NRC USE ONLY   PDR   ADDCK 05000361   PDR
	NAME OF PREPARER H. B. Ray HB Pay / William Hone 714/492-7700