



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596-5368

Docket No. 030-32816
License No. 46-23236

APR 1 1994

Anvil Corporation
1675 West Bakerview Road
Bellingham, Washington 98226

Attention: Larry Levorsen,
President

Please find enclosed the original NRC Form 591 which indicates one violation that was identified during the safety inspection performed on March 21 and 31, 1994, at the Burlington, Washington facility.

Pursuant to the provisions of 10 CFR 2.202, you are requested, within 30 days, to sign and date the enclosed NRC Form 591 which indicates that appropriate corrective actions will be taken with reference to the violation described on the form. After signing, please detach the first sheet of NRC Form 591 and return the remaining copies to me at the Region V office.

If you have any questions on this matter or concerning the inspection, please telephone Troy W. Pruett at (510) 975-0233.

Thank you for your cooperation.

Sincerely,

Gregory P. Yuhas, Chief,
Radioactive Materials Safety Branch

Enclosures:
NRC Form 591

9404150051 940401
PDR ADOCK 03032816
C PDR

IE07/11

Docket File
Inspection File
G. Cook
K. Perkins
State of Washington

bcc w/o enclosure:
M. Smith
D. Clevinger

TPruett
4/11/94

608
GYuhas
4/11/94

REQUEST COPY	REQUEST COPY	REQUEST COPY	SEND TO DCS	SEND TO PDR
YES / NO	YES / NO	YES / NO	YES / NO	YES / NO