

NRC FORM 591 PART 1
(7-91)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION


Page 1 of 1

1. LICENSEE Anvil Corporation 1675 West Bakerview Road Bellingham, Washington 98226		2. REGIONAL OFFICE REGION V U S NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE SUITE 210 WALNUT CREEK CA 94596-5368	
3. DOCKET NUMBER(S) 030-32816	4. LICENSE NUMBER(S) 46-23236-03	5. DATE OF INSPECTION March 21 and 31, 1994	

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interview personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of you **NOTICE OF VIOLATION**, which is required, as described below or attached, were in violation of NRC requirements. This form is a copy to be posted in accordance with 10 CFR 19.11.
 - A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 20.203(b),(c),(d),(e) or 34.42.
 - B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
 - C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
 - D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
 - E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
 - F. The license application dated May 29, 1992, Item 10.4.C, requires that each radiographer and radiographer's assistant be audited during an actual radiographic operation at intervals not to exceed three months.
Contrary to the above, three radiographic personnel were not audited at intervals not to exceed three months.

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE 9404150056 940401 PDR ADOCK 03032816 C PDR	DATE	SIGNATURE - NRC INSPECTOR 	DATE 4/1/94
--	------	---	----------------